#### Proj. No.: AE-0532-1003 Date: 1/24/2011 Marsh Creek, LLC 2000 E. 88<sup>th</sup> Ave. Suite 100 Attention: Alan Fetters Telephone: 907/258-0050 JAN 26 2011 Telecopy: 907/279-5710 RE: Akutan EDS Conversion & Related Upgrades AIDEA TO: AFA Agreement AEA09-022 Alaska Energy Authority 813 West Northern Lights Blvd. Anchorage, AK 99503 LETTER OF TRANSMITTAL WE ARE SENDING YOU Attached Under separate cover via the following items: ☐ Change Order ☐ Contract/NTP Copy of Letter Invoice Mylars Prints PS&E Plans ☐ Shop Drawings Specifications Other: \_\_\_\_\_

Copies	Date	No.	Description	
1		E.=	Photographic Portion of Project Progress Report 3 covering period 9/1/2010 through 10/15/2010	
	1			

THESE ARE TRANSMITTED as checked below:							
	☐ For approval	☐ Approved as submitted	☐ Resubmit copies for approval				
	☐ For your use	☐ Approved as noted	☐ Submit copies for distribution				
	☐ As requested	☐ Returned for corrections	☐ Return corrected prints				
	☐ For review & comment						
	☐ PRINTS RETURNED AFTER LOAN TO US						
REMARKS:							

Copy to: Project File

Signed:

Sharon Poston, Sr. Project Coordinator

### 9/1/2010 EXCHANGING LEAKING XFMR FOR REPLACEMENT



Leap-frogging Equipment with Lumber to Protect Homeowners' Lawns

Setting Vault



### 9/1/2010 RELOCATED TRANSFORMER 8 AT HOTEL



Stairs leading to basement of Hotel

(Inadequate space for new Xfmr &





### 9/2/2010 Terminating Transformers & Installing Streetlight Wire



Terminating New Transformer 15

Secondary Wire Staged for Streetlights




### 9/3/2010 STREETLIGHT WIRE & U-GUARD WORK



Working on Streetlights

Standing Water Preventing Switch-out of Transformer 10 & Vault











### 9/8/2010 Installing New Xfmr 2



Preparing to Set Vault




Installing Xfmr



# 9/10/2010 INSTALLING FLUSH-MOUNTED HAND HOLES






## 9/11/2010 DRAINING, TESTING, DELIVERING OLD TRANSFORMER OIL



Draining Transformer Oil



Timing PCB Test



TEXSIL®

CLOR-N-OIL 50 IS A TRADEMARK OF THE DEASIL CORATION AND IS COVERED UNDER ONE OF MORE OF FOLLOWING PATENTS: 4,873,056, 4,686,192, 5,011

**Negative PCB Test Results** 



Drained Oil Delivered to Trident for Incineration

Letter certifying PCB content of oil from Transformers not labeled as non PCB as less than 50 ppm



## 9/15/2010 TERMINATING INSIDE TENT DUE TO WEATHER








#### 9/17/2010 J-BOX TERMINATION



J-Box B



J-Box C



#### 9/19/2010 TERMINATING



J-Box D



New Transformer 12



## 9/22/2010 ALL OUTSIDE LABELING COMPLETED













**Junction Boxes** 



































**Transformers** 

#### 9/24/2010 POWERHOUSE BUS WORK








## 9/26/2010 DRAINING & TESTING OLD 3-PHASE TRANSFORMER OIL









9/28/2010
HAULING RETIRED TRANSFORMER FOR RECYCLING & PROTECTING NEW TRANSFORMER



Hauling Retired Transformer



## 9/30/2010 REPAIRING BOARDWALK & REPLACING PEDESTAL




Rebuilding Boardwalk Near Project Staging Area



New Flush-Mounted Hand Hole Which Replaced Old Secondary Pedestal at City Office

10/1/2010
COLLECTING & LOADING TRASH TO HAUL TO DUMP





## 10/3/2010 PLACING TRANSFORMER 14 & COMPLETED BOARDWALK REBUILD



Using Backhoe to Position 3-Phase Transformer 14 at Hydro



Rebuilt Boardwalk

#### 10/4/2010 PROJECT ENGINEER'S CHANGES

Transformer 1-Primary Side



Secondary Side-Before



Secondary Side-Corrected




Transformer 3 Secondary Side-Before




Transformer 3 Secondary Side-Corrected



#### 10/6/2010 – 10/9/2010 NEW STREETLIGHT WIRE & U-GUARD







### 10/10/2010 ALL TRANSFORMERS LOCKED






































Existing Service Disconnect & CT Can at School



### 10/14/2010 ALL JUNCTION BOXES LOCKED







